

SONY® Service Bulletin

NO: HIFI2-98-004

SUBJECT: DISPLAY DIM

DATE: DEC 1998

MODEL (S): MDS-S38/S39

Symptom: The customer complaint states the display is too dim.

Solution: Replace the following component on the MAIN Board:

| REF | FORMER | | NEW | |
|------|-------------|--------------|-------------|--------------|
| | DESCRIPTION | PART NUMBER | DESCRIPTION | PART NUMBER |
| C522 | 0.01 UF 20V | 1-162-306-11 | 0.1 UF 50V | 1-164-159-11 |

SONAM 569
AU02798
AU98012

Sony of Canada Ltd.

115 Gordon Baker Road, Willowdale, Ontario M2H-3R6
NATIONAL LAB - CONSUMER SERVICE