

# SONY® Service Bulletin

NO: HIFI2-99-015

SUBJECT: PART NUMBER CORRECTION

DATE: NOV 1999


MODEL (S): MDS-S38, MDS-S39, MDS-JE500, MDS-JE510

**Symptom:** The part number and description listed in the Service manual for the Lever (limiter) is incorrect.

**Solution:** Use the following number when ordering:

REP	DESCRIPTION		PART NUMBER	
	INCORRECT	CORRECT	INCORRECT	CORRECT
254	SLIDER(CAM)	LEVER(LIMITER)	4-983-437-01	4-979-901-21

## 7-4. MECHANISM DECK SECTION 2 (MDM-3B)



Sony of Canada Ltd.

115 Gordon Baker Road, Toronto, Ontario M2H-3R6  
NATIONAL LAB - CONSUMER SERVICE

AU99022  
SONAM 602