

# SONY®

## Service Bulletin

NO: HIFI2-02-004

---

**SUBJECT:** No Operation after BD board is replaced

---

**DATE:** 11/11/2002

**MODEL(S):** MDSJE470, MDSJB940, MXDD40, MXDD5C  
MDSPC3, MDM7SERIES

---

**Symptom:** The unit does not operate when a new MD BD board is installed.

**Solution:** Remove EEPROM IC171 from the original MD BD board and put it on the new MD BD board. Electrical adjustment is not needed unless the optical block has been replaced.

E17084643  
HA02STM514

Sony of Canada Ltd.

115 Gordon Baker Road, Toronto, Ontario M2H-3R6  
**TECHNICAL SERVICE – AVIT**