

SONY®

Service Bulletin

NO:GA2-00-009

SUBJECT: Part number for M901

DATE: September 2000	MODEL (S): ZS-D7
-----------------------------	-------------------------

The part number A-3320-330-A for M901 indicated on page 81 of the Service Manual is incorrect. The correct part number for **M901 "Turntable Motor"** is **A-3303-971-A**.

GA01400

Sony of Canada Ltd. 115 Gordon Baker Road, Toronto, Ontario M2H-3R6
NATIONAL LAB - CONSUMER SERVICE