

# SONY®

## Service Bulletin

NO:HIFI2-98-002

**SUBJECT:** PART NUMBER CORRECTION - REFERENCE NO. 254, LEVER (LIMITER)

**DATE:** SEP 1998

**MODEL (S):** MDS-JE500, MDS-EJ510, MDS-S37, MDS-S38

**Symptom:** The part number listed in the Service Manual for Ref # 254, Lever (Limiter), is incorrect.

**Solution:** Please note the correct part number as shown below.

REF	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
254	LEVER (LIMITER)	4-983-437-01	4-979-901-21

Sony of Canada Ltd.

115 Gordon Baker Road, Willowdale, Ontario M2H-3R6  
NATIONAL LAB - CONSUMER SERVICE

AU01298  
SONAM565