



# Repair Tips

---

**SUBJECT:** Part number correction for Bottom Panel Assy

---

**DATE:** Aug/2002

**MODEL (S):** MZN1

---

**Symptom:** The part number in the service manual for the Bottom Panel Ass'y is incorrect

**Solution:** Use the part numbers listed below to order the Bottom Panel Ass'y in Silver or Blue finish.

Reference #	Description	Part #
51	Bottom panel assembly, silver	X-3382-443-1
51	" " " , blue	X-3382-438-1

**Submitted By :** U.S. ESI /wd

Sony of Canada Ltd.

115 Gordon Baker Road, Toronto, Ontario M2H-3R6  
NATIONAL LAB – AVIT