

SONY®

Service Bulletin

NO:HIF12-00-002

SUBJECT: Part Number Missing - Battery Case For LIP-12 Optional Battery

DATE: July 2000


MODEL (S): MZ-R3

Please discard the previous issued bulletin MD-96-014

Symptom: The part number for the LIP-12 Battery Case, which is shown on page 29 of the Owner's Manual, is not listed in the parts list.

Solution: Please add the following part number to the Service Manual.

REF DESCRIPTION	PART NUMBER
BATTERY CASE FOR LIP-12	1-759-048-31



JapanTFR

NATIONAL LAB - CONSUMER SERVICE